Roll No.	
----------	--

3013

B. Tech 1st Semester (Common for All Branches) Examination – December, 2019

WORKSHOP TECHNOLOGY

Paper: ESC-ME-102-G

Time: Three Hours]

[Maximum Marks: 75

Before answering the questions, candidates should ensure that they have been supplied the correct and complete question paper. No complaint in this regard, will be entertained after examination.

Note: Question No. 1 is compulsory having, ten parts and each part is of 2.5 marks total of 25 marks and remaining questions is of 12.5 marks. And attempt one question from each Unit.

- 1. (a) Name any two Machining Process.
 - (b) What is joining process?

(c)	What are	important	material	first	aid	box	shoul	d
	have?							

- (d) Define hot working.
- (e) What is piercing?
- (f) Draw Skelton piece pattern.
- (g) Name the parts of shaper machine.
- (h) Write the definition of welding.
- (i) What is a shift defect in casting?
- (j) What is knurling?

 $2.5 \times 10 = 25$

UNIT - I

- 2. Explain the various methods of preventing the accidents.
- **3.** What is Plant Layout and discuss the various types of Plant Layout?

UNIT - II

4. Explain Hot rolling and also explain various types of rolling.12.5

5. Explain the various Sheet Metal Operations. 12.5

UNIT - III

6. Discuss the various parts of lathe machine. 12.5

7. Discuss the working of Cupola Furnace. 12.5

UNIT - IV

- 8. Explain the welding process and classify the various types Welding Processes.12.5
- $\textbf{9.} \ \ \text{Discuss the difference between Soldering \& Brazing}.$

12.5